# Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: WILLIE 2-36AH

Field Name: BATTLEVIEW Well File #: 22857

Date Incident:3/10/2016Time Incident:08:32Facility ID Number:County:WILLIAMSTwp:159Rng:95Sec:36Qtr:

Location Description:

Submitted By: Timothy Ilse Received By:

Contact Person: Ben Tarap

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	
Oil	1	Barrels	1	Barrels	
Brine	8	Rarrels	8	Rarrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

N/A

Followup Units

## Potential Environmental Impacts:

Well site soil

## Action Taken or Planned:

Removed all visibly contaminated material and replaced with clean fill.

Wastes Disposal Location: 13 Mile Disposal

Agencies Involved: Called John Rumppe at 9:28 am on 3/10/2016

#### **Updates**

Date: 3/10/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Release, due to a tank overflow, remained within diking according to the report. NDIC retains oversight.